

M 6.3, 182km W of Port Hardy, Canada


Origin Time: 2019-12-25 03:36:02 UTC (Tue 18:36:02 local)

Location: 50.5828° N 129.9987° W Depth: 10.0 km

FOR TSUNAMI INFORMATION, SEE: tsunami.gov


Created: 1 day, 0 hours after earthquake

Estimated Fatalities



Green alert for shaking-related fatalities and economic losses. There is a low likelihood of casualties and damage.

Estimated Economic Losses




Estimated Population Exposed to Earthquake Shaking

| | | | | | | | | | | |
|---|-----------------------|----------|--------|-------|----------|----------|-------------|------------|----------|----------|
| ESTIMATED POPULATION EXPOSURE (k=x1000) | | —* | 18k* | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| ESTIMATED MODIFIED MERCALLI INTENSITY | | I | II-III | IV | V | VI | VII | VIII | IX | X+ |
| PERCEIVED SHAKING | | Not felt | Weak | Light | Moderate | Strong | Very Strong | Severe | Violent | Extreme |
| POTENTIAL DAMAGE | Resistant Structures | None | None | None | V. Light | Light | Moderate | Mod./Heavy | Heavy | V. Heavy |
| | Vulnerable Structures | None | None | None | Light | Moderate | Mod./Heavy | Heavy | V. Heavy | V. Heavy |

*Estimated exposure only includes population within the map area.

Population Exposure



Structures

Overall, the population in this region resides in structures that are highly resistant to earthquake shaking, though some vulnerable structures exist. The predominant vulnerable building type is low-rise reinforced/confined masonry construction.

Historical Earthquakes

| Date (UTC) | Dist. (km) | Mag. | Max MMI(#) | Shaking Deaths |
|------------|------------|------|------------|----------------|
| 2004-11-02 | 174 | 6.6 | IV(18k) | — |
| 1978-07-25 | 168 | 5.6 | V(11k) | — |
| 2004-07-19 | 238 | 6.3 | V(12k) | — |

Selected City Exposure

from GeoNames.org

| MMI | City | Population |
|-----|------|------------|
|-----|------|------------|

bold cities appear on map.

(k = x1000)

PAGER content is automatically generated, and only considers losses due to structural damage.

Limitations of input data, shaking estimates, and loss models may add uncertainty.

<https://earthquake.usgs.gov/earthquakes/eventpage/us70006qt7#pager>

Event ID: us70006qt7